

General Environmental Incident Summary

Incident: 3248 **Date/Time Notice:** 3/16/2014 0930 **DEM Incident No:**
Responsible Party: ONEOK Rockies Midstream
Date Incident: 3/14/2014 **Time Incident:** 1100 **Duration:** 1 hours
County: McKenzie **Twp:** 147 **Rng:** 104 **Sec:** 3 **Qtr:**
Lat: 47.58282 **Long:** -103.91530 **Method:** Derived from TRS
Location Description: T147N, R104W, Section 3
Approximately 3.5 miles East-South-East of the Grasslands Natural Gas Processing Plant
Submitted By: Jason Lyons **Affiliation:**
Address: 2700 Lincoln Ave.
City: Sidney **State:** MT **Zip:** 59270

Received By:

Contact Person: Jason Lyons
2700 Lincoln Ave
Sidney, MT 59270

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Pipeline Leak

Description of Released Contaminant: Dry, Sweet Natural Gas

Volume Spilled: 1.00 cubic yards **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

The cause is unknown. The well site is partially under water/ice. Pipeline will be excavated as soon as water is pumped away.

Risk Evaluation:

There were no immediate risks to human health.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 01 - air

Potential Environmental Impacts:

There were no impacts to surface water or groundwater. Site surface soil shows no evidence of release.

Action Taken or Planned:

Line has been blocked in. There is currently no evidence of a release. There is no evidence of hydrocarbon impact on the ground surface or in the standing water on-site.

Wastes Disposal Location: Release was dry gas only and there was no impact to surface soil or to standing water on site. Therefore, there are no recovered wastes.

Agencies Involved: NDDDES

Updates

Date: 3/16/2014

Status: Reviewed; Followup Required

Staff: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary to confirm no natural gas liquids released.

Date: 3/18/2014

Status: Inspected

Staff: Espe, Brady

Updated Volume:

Notes:

The weather was 40 °F, with wind from the northeast at 15-20 mph. The pipeline valve is located in a federal pasture on the south side of highway. I walked around the area and did not see any impacts. I also looked around the well to the north and did not see any issues. No further followup is required at this time.